

L P C F C O 5 5 C  
(1) (8) (9)

ILD041889023

OBSERVATION REPORT - SITE INVENTORY NO. 11905002  
(11) (18)MADISON

CO. - L.P.C.

Region # 5Date 07/23/81

(20) (25)

HARTFORD

(Location)

1 CLARK OIL & REFINING

(Responsible Party)

Letter Sent (Yes or No) No

(26)

Samples Taken: Yes ( ) No (X)

Time: From 09:45 a.m.Weather RAINY, MUDDY, 56.5°

Ground Water ( ) Surface ( ) Other ( )

To 12:00 p.m.

Photos Taken: Yes ( ) No (X)

Interviewed S. VAN PETTENInspector D M S

(27) (29)

Previous Inspection

Previous Correspondence

Site Open: Yes (X) No ( )

OPERATIONAL STATUS:

TYPE OF OPERATION:

AUTHORIZATION:

Operating (X)

Landfill ( )

Storage (X)

E.P.A. Permit (X)

Temporarily Closed ( )

Random Dump ( )

Salvage ( )

Variance ( )

Closed Not Covered ( )

Other GENERATOR (X)

A.C.D. ( )

21(e) ( )

Closed and Covered ( )

Quantity Received Daily(1-6) 1

(30)

Board Order ( )

Illegal (5) ( )

(31)

IMPROVED

RECEIVED

JUL 27 1981

LPC 4 1/79 5,000

SAME

DETERIORATED

E.P.A. - D.L.P.C.

I S or D

(62)

STATE OF ILLINOIS

GENERAL REMARKS: Clark Oil & Refining Corporation principally refines petroleum products. Mr. S.L. Van Petten, C.E. Knipping, and G.E. Burkhardt of Clark Oil were interviewed. Mr. Van Petten and Mr. Knipping accompanied me on the inspection of the storage/treatment tanks. At this time, several of the hazardous wastes were not present, as the sludge had not yet been removed from the bottom of the tanks. The site appears to have met most of the criteria under Interim Status Standards, with a few minor deficiencies. A signal system to notify when an evacuation is needed is not listed in

INTERVIEW: the Contingency Plan. Other areas regarding personnel training, safety equipment, inspections, waste analysis, and manifesting appear to have been adequately addressed.

DIAGRAM:

EPA Region 5 Records Ctr.



295826

